

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-------|------|---|---|------------------|---------|------------------|
| L4 | 39 | current near sensor near stator | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/09/15 09:42 |
| L5 | 1 | current near sensor near stator and hall | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/09/15 09:42 |
| L6 | 15 | ("3329869" "3358208" "3404313" "4041541" "4379291" "4733117" "5003208" "5571568" "5798591" "5925952" "5939813" "5998894").PN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/15 09:44 |
| L7 | 3 | 6 and hall | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/15 09:48 |
| L8 | 97 | (current near sensor) same stator and hall | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/15 09:49 |
| S1 | 0 | "10/821,015" | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/09/14 10:14 |
| S2 | 237 | 396/508.ccls. | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/09/14 11:21 |
| S3 | 153 | "asia optical co" | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/09/14 11:24 |
| S4 | 4 | "asia optical co" and (diaphragm aperture) | US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/09/14 11:24 |
| S5 | 6 | ("4633357" "4842387" "5241251" "5850277" "6510282" "6710563").PN. | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/15 09:44 |

| | | | | | | |
|-----|------|--|------------------------------|----|-----|------------------|
| S6 | 2 | S5 and sensor | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 15:41 |
| S7 | 68 | "current sensor" same inside same motor | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 15:58 |
| S8 | 1276 | "current sensor" same in same motor | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 15:58 |
| S9 | 29 | "current sensor" same in same motor and camera | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 16:03 |
| S10 | 1325 | (current near sensor) same in same motor | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 16:19 |
| S11 | 42 | (current near sensor) same in same motor and "hall sensor" | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 16:20 |
| S12 | 14 | "hall sensor" near "current sensor" | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 16:29 |
| S13 | 51 | "hall sensor" near current | US-PGPUB; USPAT; USOCR | OR | OFF | 2005/09/14 16:29 |